

**West Virginia Chemical Leak Etowah,
Kanawha County, West Virginia TDD No.
TL01-14-01-001**



1/16/2014

Contractors developing the monitoring wells at the base of the slope, downgradient from the tanks.



1/16/2014

Contractors excavating the trench along the slope below the northeastern area of the tank farm. A bentonite layer is placed in the trench.



1/16/2014

Contractors placing liner over the rear slope



1/16/2014

Fence installed along the crest of the river bank